



PRESSURE/TORQUE CONVERSION CHART

**35IBT**

PRESSURE IN PSI	FT. LBS.	N-m
1500	5146	6977
1600	5478	7427
1800	6143	8329
2000	6808	9230
2200	7522	10198
2400	8237	11168
2600	8951	12136
2800	9666	13105
3000	10380	14073
3200	11062	14998
3400	11745	15924
3600	12427	16849
3800	13110	17775
4000	13792	18699
4200	14502	19662
4400	15211	20623
4600	15921	21586
4800	16630	22547
5000	17340	23510
5200	18050	24472
5400	18759	25433
5600	19469	26396
5800	20178	27357
6000	20888	28320
6200	21614	29304
6400	22339	30287
6600	23065	31272
6800	23790	32254
7000	24516	33239
7200	25241	34222
7400	25966	35205
7600	26690	36186
7800	27415	37169
8000	28140	38152
8200	28825	39081
8400	29509	40008
8600	30194	40937
8800	30878	41864
9000	31563	42793
9200	32257	43734
9400	32950	44674
9600	33644	45615
9800	34337	46554
10000	35031	47495

